




MAZATROL FUSION 640T

MILLING UNIT INFORMATION




MAZATROL FUSION 640T

MDR OUT
MDR FCE

POINTS TO NOTE

1. The control automatically positions the tool clear of the material by a clearance amount set in parameters.
2. Positions to the right of Z zero are defined as negative z co-ordinates.
3. When using the "BOTTOMED" drill cycles, the programmed depth is based on the depth of the drill point in the material.
4. When using the "THROUGH" drill cycles, the programmed depth is based on the full diameter drilling depth - material length. The control automatically allows for the extra drilling depth by referring to the TOOL DATA page (for the drilling point allowance), and to a parameter, for the through clearance.
5. Feedrates at the start and finish of the drilling can be altered by parameters.
6. Cycle Types: #0 = peck, feed retract. #1 = peck, chip clear.
#2 = peck, chipbreak. #3 = ream. #4 = #1 & #2 combination.



NB. S = starting point. D = depth.

MTP OUT**MTP FCE**

POINTS TO NOTE

1. The control automatically positions the tool clear of the material by a clearance amount set in a parameter.
2. Positions to the right of Z zero are defined as negative Z co-ordinates.
3. The actual depth in the program is based on the full thread length.
4. The control automatically allows for the taper lead section of the tap by a parameter setting.
5. The control automatically allows for the taper elongation when retracting, by a parameter setting.

NB. S = starting point. D = depth.


BOR OUT

BOR FCE


POINTS TO NOTE

1. The control automatically positions the tool clear of the material by a clearance amount set in a parameter.
2. Positions to the right of the Z zero are defined as negative z co-ordinates.
3. The actual depth in the program is based on the tool boring depth. Therefore, allowances must be included if the tool is boring through.
4. For INTEGREX type machines, spindle orientation, and tool tip relief are possible, but only when the tool is mounted horizontally.
5. Cycle types: #0 = Feed in, Feed out.
#1 = Feed in, Orient mill spindle (Integrex type m/c only),
Rapid out.
#2 = Feed in, Orient mill spindle, Tool retract, (Integrex type m/c only), Rapid out.

N.B S = Starting point, D = Depth.

MGV OUT




POINTS TO NOTE

1. The control automatically positions the tool clear of the material by clearance amounts set in parameters.
 2. Positions to the right of the Z zero, are defined as negative Z co-ordinates.
 3. The center line detail of the MGV feature must be a straight line parallel to the Z axis, and pass through the component center line.(Non Y axis machines.)
 4. The finish tool diameter must be equal to the required slot width.
(Non Y axis machines.)
 5. While cutting, the C axis is clamped.
 6. Cutting patterns: #0 = Uni-directional. #1 = Bi-directional.
#2 = CW cut.* #3 = CCW cut.*
- (*) For Y axis machines only, and for these cycles, Wall Fin Allowance = Axial Fin Allowance.

N.B S=Start point, E=Final point, D=Depth, W=Width, F=Main feed direction.
(Start pt, Final pt and Main feed directions can be reversed.)

MGV FCE




POINTS TO NOTE

1. The control automatically positions the tool clear of the material by clearance amounts set in parameters.
2. Positions to the right of the Z zero are defined as negative Z co-ordinates.
3. The **centre line** detail of the MGV feature, must be a straight line on the face of the component, and must pass through the component centre.
4. The finish tool diameter must be equal to the required slot width.
5. While cutting, the C axis is clamped.
6. Cutting patterns: #0 = Uni-directional. #1 = Bi-directional.

N.B S = Start point. E = Final point. D = Depth. W = Width. F = Main feed direction.


(Start pt, Final pt and Main feed direction, can be reversed).



POINTS TO NOTE:


1. The control automatically positions the tool clear of the material by clearance amounts set in parameters.
2. Positions to the right of Z zero are defined as negative Z co-ordinates.
3. This process positions the cutter centre ON the line defined.
4. While machining using a LCT OUT unit, once a desired cut radius has been set the machine uses Z-Axis and C-Axis (or Y-Axis, with option) to produce the profile.
5. While machining using a LCT FCE unit, once a desired cut radius has been set the machine uses X-Axis and C-Axis (or Y-Axis, with option) to produce the profile.
6. Initial positioning of the cutter must be specified by START POINT before profiling of the feature begins.

N.B. W= width of groove



POINTS TO NOTE:


1. The control automatically positions the tool clear of the material by clearance amount set in parameters.
2. Positions to the right of Z zero are defined as negative Z co-ordinates.
3. This process positions the cutter to the right-hand side of the line defined.
4. While machining using a RGT OUT unit, once a desired cut radius has been set the machine uses Z-Axis and C-Axis (or Y-axis, with option) to produce the profile.
5. While machining using a RGT FCE unit, once a final point in Z-Axis has been set the machine uses X-Axis and C-Axis (or Y-axis, with option) to produce the profile.
6. Initial positioning of the cutter must be specified by START POINT before profiling of the feature begins.



POINTS TO NOTE:

1. The control automatically positions the tool clear of the material by clearance amounts set in parameters
2. Positions to the right of the Z zero are defined as negative Z co-ordinates.
3. This process positions the cutter to the left-hand side of the line defined.
4. While machining using a LFT OUT unit, once a desired cut radius has been set the machine uses Z-Axis and C-Axis (or Y-Axis, with option) to produce the profile.
5. While machining using a LFT FCE unit, once a desired cut radius has been set the machine uses X-Axis and C-Axis (or Y-Axis, with option) to produce the profile.
6. Initial positioning of the cutter must be specified by START POINT before profiling of the feature begins.

NOTES RELATING TO MDR/MTP UNIT





When creating a MDR/MTP process the menu options will ask you to select from the choices below (BAK, only on 2nd spindle machines).



The choice between normal and highlighted options affect tool retraction between hole positions. See below:

- OUT** : Outer periphery (return to the initial point)
- OUT** : Outer periphery (return to the reference point)
- FCE** : Front face (return to the initial point)
- FCE** : Front face (return to the reference point)
- BAK** : Back face (return to the initial point)
- BAK** : Back face (return to the reference point)

MDR/MTP

MDR/MTP




NOTE:

The differences in action will occur between ‘Return to the initial point’ and ‘Return to the reference point’, only if multiple holes are machined during one unit.

If ‘Return to the initial point’ is selected, the tip of the tool will return to the initial point (position that is away from the maximum-outside-diameter part or edge of the workpiece by the safety profile clearance amount) each time a hole is machined.

If ‘Return to the reference point’ is selected, the tip of the tool will return to the reference point (position at which the tool is away from the programmed starting point by the safety profile clearance amount) after machining of the first hole, and then start machining the next hole.

Before selecting ‘Return to the reference point’, check that during movement to the following hole positions, the tool tip will not interfere with any protruding sections of the workpiece or with any other



MAZATROL FUSION 640T



MAZATROL FUSION 640T


POLAR CO-ORDINATE SYSTEM



MAZATROL FUSION 640T

Mazak
EUROPE

TITLE: POLAR CO-ORDS



POLAR CO-ORDINATES ARE
SPECIFIED IN TERMS OF RADIUS
& ANGULAR POSITION, RADIATING
FROM MACHINE CENTRE LINE.

180 DEG


DRAWN BY: PW
DRG. No.: DATE: 12/98
MATERIAL:

Setting sequence data

UNo.	UNIT	#	DIA	DEPTH	DEP-1	DEP-2	DEP-3	C-SD	FEED	TOOL
*	MDR ***	*	***	***	***	***	***	***	***	***
SEQ	SHP	SPT-R/x	SPT-TH/y	SPT-Z		NUM.	ANGLE		TYPE	
1	①	②	③	④		⑤	⑥		⑦	

①SHP

The following menu will be displayed when the cursor is placed at this item.



Select (a) or (b) from the menu above.

The data of the displayed menu represent hole-drilling position patterns.

- Select **POINT** if one hole is to be drilled at any position.
 - Select **CIRCLE** to drill multiple holes at an equal pitch along the same circumference with its center set at the program origin.

② SPT-R/x, ③ SPT-TH/y ④ SPT-Z

Specify a drilling start position for the hole you are going to make.




Set either the R-θ coordinates or x-y coordinates of the starting point in items ② and ③.

- To use the R-θ coordinates, set the radius and the angle as they are.
 - To use the x-y coordinates, set data after reversing **x-y INPUT** display by pressing its menu key.

Set the Z-coordinate of the starting point in data filed ④.


Note 1: For **BAK** and **BAK** only R-θ coordinates can be entered (a restriction because of the 1-degree orientation function of the No. 2 spindle).

Note 2: The manner of assigning a sign for θ is opposite between BAK and OUT or ECE.



Note 3: The C-axis program origin position ($\theta = 0^\circ$) can be taken at any point convenient for programming.

Example: To drill holes **A**, **B** and **C** at the positions shown below.



- 1) Set the following data if you have taken the position of (d) as $\theta = 0^\circ$:


	UNo.	UNIT	#	DIA	DEPTH	DEP-1
	*	MDR OUT	*	***	***	***
	SEQ	SHP	SPT-R/x	SPT-TH/y	SPT-Z	
Hole A →	1	PNT	50.	0.	20.	
Hole B →	2	PNT	50.	-120.	20.	
Hole C →	3	PNT	50.	-180.	20.	

- 2) Set the following data if you have taken the position of (e) as $\theta = 0^\circ$:

	UNo.	UNIT	#	DIA	DEPTH	DEP-1
	*	MDR OUT	*	***	***	***
	SEQ	SHP	SPT-R/x	SPT-TH/y	DEP-Z	
Hole A →	1	PNT	50.	60.	20.	
Hole B →	2	PNT	50.	-60.	20.	
Hole C →	3	PNT	50.	-120.	20.	

Note 4: If you have selected **CIRCLE** for data item ①, you can set the starting point at a position other than the actual drilling position.

Example: To drill holes at the positions shown below:



Point *A* can be set as the starting point.

In this case, however, 1 (No machining at the starting position) must be set in data field ⑦, **TYPE**, described below.

UNo.	UNIT	#	DIA	DEPTH	DEP-1	DEP-2	
*	MDR OUT	*	***	***	***	***	
SEQ	SHP	SPT-R/x	SPT-TH/y	SPT-Z	NUM.	ANGLE	TYPE
1	CRC	50.	0.	20.	4.	72.	1

⑤ NUM.

- If **POINT** is selected for data item ①:
A ♦ mark will be displayed in this position to indicate that no data can be set.
- If **CIRCLE** is selected for data item ①:
Set the number of holes to be drilled.

⑥ ANGLE


- If **POINT** is selected for data item ①:
A ♦ mark will be displayed in this position to indicate that no data can be set.

- If **CIRCLE** is selected for data item ①:

Set a drilling pitch angle (θ in the diagram below) for the holes you are going to make.

If $\theta > 0$, the machining order is **a → b → c → d → e**.

If $\theta < 0$, the machining order is **a → e → d → c → b**.



⑦ TYPE

- If **POINT** is selected for data item ①:

A ♦ mark will be displayed in this position to indicate that no data can be set.


- If **CIRCLE** is selected for data item ①:

Specify whether the hole is to be drilled at the starting position whose data has been specified in data items ② to ④.

Set 0 if drilling is to be done.


Set 1 if drilling is not to be done.

PROGRAMMING EXAMPLE NO.6










MAZATROL FUSION 640T



MILLING TOOLS FOR PROGRAM EXAMPLE No 6





MAZATROL FUSION 640T

UNo. MAT OD-MAX ID-MIN LENGTH RPM FIN-X FIN-Z WORK FACE
0 AL 160. 38. 120. 3000 0.4 0.1 0.

UNo. MODE

1MTR OUT

SEQ	SHP	SPT-X	SPT-Z	FPT-X	FPT-Z	RADIUS
1LIN		*	*	83.	48.	*
2LIN		*	*	160.	80.	*
3LIN		*	*	50.	120.	*

UNo. MODE # 1 # 2 # 3 # 4 # 5 # 6 # 7 # 8 # 9 #10 #11 #12
2M 8

UNo. MODE # CPT-X CPT-Z RV FV R-FEED R-DEP. R-TOOL F-TOOL
3BAR FCE 0 160. 48. 375 700 0.4 1. 3
SEQ SHP S-CNR SPT-X SPT-Z FPT-X FPT-Z F-CNR/\$ RADIUS/Ø ROUGH
1LIN * * 83. 50. *

UNo. MODE # CPT-X CPT-Z RV FV R-FEED R-DEP. R-TOOL F-TOOL
4BAR OUT 0 83. 0. 375 700 0.4 5.5 3
SEQ SHP S-CNR SPT-X SPT-Z FPT-X FPT-Z F-CNR/\$ RADIUS/Ø ROUGH
1LIN C 1. * * 72. 40. *
2LIN * * 78. 50. *

UNo. MODE # CPT-X CPT-Z RV FV R-FEED R-DEP. R-TOOL F-TOOL
5BAR OUT 0 160. 0. 375 700 0.4 5.5 2
SEQ SHP S-CNR SPT-X SPT-Z FPT-X FPT-Z F-CNR/\$ RADIUS/Ø ROUGH
1LIN C 1. * * 72. 40. * Rgh 4
2LIN * * 78. 50. * Rgh 4
3LIN C 0.5 * * 160. 50.5 *

UNo. MODE # CPT-X CPT-Z RV FV R-FEED R-DEP. R-TOOL F-TOOL
+ 6BAR BAK 0 160. 80. 375 700 0.35 3. 4A 4A
SEQ SHP S-CNR SPT-X SPT-Z FPT-X FPT-Z F-CNR/\$ RADIUS/Ø ROUGH
1LIN * * 88.564 60. * Rgh 4
2TPR 88.564 60. 55. 80. 50. Rgh 4

UNo. MODE # No. PITCH WIDTH FINISH RV FV FEED DEP. R-TOOL F-TOOL
7GRV OUT 1 1 6. 0. 120 139 0.1 2. 8 8
SEQ S-CNR SPT-X SPT-Z FPT-X FPT-Z F-CNR ANGLE ROUGH
1 72. 34. 66. 34. * Rgh 4

UNo. MODE # CPT-X CPT-Z RV FV R-FEED R-DEP. R-TOOL F-TOOL
8BAR IN 0 38. 0. 375 700 0.4 5. 6 7
SEQ SHP S-CNR SPT-X SPT-Z FPT-X FPT-Z F-CNR/\$ RADIUS/Ø ROUGH
1LIN C 1.5 * * 44. 10. * Rgh 4
2TPR 44. 10. 50. 14.5 -33.69 Rgh 4
3LIN * * 50. 60. * Rgh 4
4LIN C 0.5 * * 38. 60.5 *

UNo. MODE GRV-WID DEPTH FIN-1 FIN-2 RV FV R-FR 1 R-FR 2 R-TOOL F-TOOL
9LFT FCE 25. 14.5 0. 0. 150 300 0.15 0.25 10A 10A
SEQ SHP FPT-R/x FPT-An/y FPT-Z F-CNR RADIUS ROUGH
1STP 36. 135. 0. * Rgh 4
2LIN 36. 45. * * Rgh 4


UNo. MODE # DIA. DEPTH DEP-1 DEP-2 DEP-3 V FEED TOOL
10MDR OUT 2 8. 15. 8. 3. 3. 25 0.032 10C
SEQ SHP SPT-R/x SPT-An/y SPT-Z NUM. ANGLE TYPE
1PNT 25.4 90. 7.25 * * *



MAZATROL FUSION 640T


UNo.	MODE	#	DIA.	DEPTH	DEP-1	DEP-2	DEP-3	V	FEED	TOOL	
11MDR	FCE	2	13.	15.	13.	3.	3.	25	0.200	11A	
SEQ	SHP	SPT-R/x	SPT-An/y	SPT-Z					NUM.	ANGLE	TYPE
1CIR		60.	0.	50.					5	-45.	0
UNo.	MODE	#	DIA.	DEPTH	DEP-1	DEP-2	DEP-3	V	FEED	TOOL	
12MDR	FCE	2	10.2	15.	10.2	3.	3.	25	0.200	10D	
SEQ	SHP	SPT-R/x	SPT-An/y	SPT-Z					NUM.	ANGLE	TYPE
1PNT		50.	60.	50.					*	*	*
2PNT		50.	120.	50.					*	*	*
UNo.	MODE		NOM-DIA	PITCH		DEPTH	DWELL	V		TOOL	
13MTP	FCE		M12.	1.75		15.	0.	8		9C	
SEQ	SHP	SPT-R/x	SPT-An/y	SPT-Z					NUM.	ANGLE	TYPE
1CIR		50.	60.	50.					2	60.	0
UNo.	MODE	COUNTER	RETURN	WK.No.	CONT.	NUM.		SHIFT			
14END		0	0		0	0		0.			

PROGRAMMING EXAMPLE N.7











MAZATROL FUSION 640T



TOOLS FOR PROGRAM EXAMPLE No 7





MAZATROL FUSION 640T

UNo. MAT OD-MAX ID-MIN LENGTH RPM FIN-X FIN-Z WORK FACE
0 AL 150. 0. 80. 3000 0.4 0.1 2.

UNo. MODE # 1 # 2 # 3 # 4 # 5 # 6 # 7 # 8 # 9 #10 #11 #12
1M 8

UNo. MODE
2EDG FCE RV FV R-FEED R-DEP. R-TOOL F-TOOL
SEQ SPT-X SPT-Z FPT-X FPT-Z
1 150. 2. 0. 0. ROUGH
Rgh 5

UNo. MODE # CPT-X CPT-Z RV FV R-FEED R-DEP. R-TOOL F-TOOL
3BAR OUT 0 150. 0. 375 700 0.4 5.5 1 2
SEQ SHP S-CNR SPT-X SPT-Z FPT-X FPT-Z F-CNR/\$ RADIUS/Ø ROUGH
1LIN C 1. * * 140. 40. * Rgh 5
2TPR 140. 40. 150. 48.66 30. Rgh 5

UNo. MODE # DIA. DEPTH DEP-1 DEP-2 DEP-3 V FEED TOOL
4MDR FCE 1 8.7 20. 8.7 3. 3. 62 0.034 11A
SEQ SHP SPT-R/x SPT-An/y SPT-Z SPT-Y/C CTR1/PITCH CTR2 NUM. ANGLE TYPE
1CIR 50. 75. 0. * * * 4 60. 0

UNo. MODE NOM-DIA PITCH DEPTH DWELL V TOOL
5MTP FCE M10. 1.5 12. 0. 20 11A
SEQ SHP SPT-R/x SPT-An/y SPT-Z SPT-Y/C CTR1/PITCH CTR2 NUM. ANGLE TYPE
1CIR 50. -105. 0. * * * 4 -60. 0

UNo. MODE # GRV-WID DEPTH FINISH RV FV R-FR 1 R-FR 2 R-TOOL F-TOOL
6MGV OUT 1 6. 4. 0.1 76 76 0.04 0.02 12A 12A
SEQ SPT-R SPT-An SPT-Z SPT-Y FPT-R FPT-Z ROUGH
1 70. 0. 16. 0. * 35. Rgh 5
2 70. -90. 16. 0. * 35. Rgh 5
3 70. -180. 16. 0. * 35. Rgh 5

UNo. MODE GRV-WID DEPTH FIN-1 FIN-2 RV FV R-FR 1 R-FR 2 R-TOOL F-TOOL
7LFT FCE 20. 10. 0.1 0.1 83 101 0.1 0.05 9A 9A
SEQ SHP FPT-R/x FPT-An/y FPT-Z FPT-Y/C F-CNR RADIUS ROUGH
1STP 70. -105. 0. * * Rgh 5
2LIN 70. -165. * * * Rgh 5
3LIN 70. -225. * * * Rgh 5
4LIN 70. -285. * * * Rgh 5
5LIN 70. -345. * * * Rgh 5
6LIN 70. -45. * * * Rgh 5
7LIN 70. -105. * * * Rgh 5

UNo. MODE COUNTER RETURN WK.No. CONT. NUM. SHIFT
8END 0 0 0 0 0.



MAZATROL FUSION 640T




MAZATROL FUSION 640T


CARTESIAN CO-ORDINATE SYSTEM



MAZATROL FUSION 640T



TITLE: CARTESIAN CO-ORDS




CARTESIAN INPUT ALLOWS
A POSITION TO BE SPECIFIED
IN TERMS OF X & Y CO-ORDS.
RADIATING FROM WORK-PIECE
CENTRE.

DRAWN BY:	PW
DRG. No.:	DATE: 12/98
MATERIAL:	


Examples using CARTESIAN co-ordinates in comparison to POLAR co-ordinates.

LINE



R-θ-Z-
input


SEQ	SHP	FPT-R/x	FPT-TH/y	FPT-Z	CNR	RADIUS	RGH
1	STP	24.	20.	10.	◆	◆	
2	LNE	26.	70.		◆	◆	



x-y-Z-
input


SEQ	SHP	FPT-R/x	FPT-TH/y	FPT-Z	CNR	RADIUS	RGH
1	STP	18.	7.	10.	◆	◆	
2	LNE	5.	13.		◆	◆	

CW ARC



**R-θ-Z-
input**


SEQ	SHP	FPT-R/x	FPT-TH/y	FPT-Z	CNR	RADIUS	RGH
1	STP	26.	20.	10.	◆	◆	
2	CW	24.	70.	◆		30.	




**x-y-Z-
input**

SEQ	SHP	FPT-R/x	FPT-TH/y	FPT-Z	CNR	RADIUS	RGH
1	STP	20.	8.	10.	◆	◆	
2	CW	4.	18.	◆		30.	

CCW ARC




R-θ-Z- input	SEQ	SHP	FPT-R/x	FPT-TH/y	FPT-Z	CNR	RADIUS	RGH
	1	STP	20.	15.	10.	◆	◆	
	2	CCW	30.	80.	◆		45.	



x-y-Z- input	SEQ	SHP	FPT-R/x	FPT-TH/y	FPT-Z	CNR	RADIUS	RGH
	1	STP	18.	5.	10.	◆	◆	
	2	CCW	5.	20.	◆		45.	

- Set data with a minus sign if the center angle of the arc is to exceed 180 degrees.

Example: If the machining into the pattern shown below is to be performed, set data shown below to one of the diagrams. (x-y-Z input)




For arcs, the two patterns shown in the diagram above are usually recognized as machining patterns even if the start point, end point and radius are designated. Set radius data as a plus value if the center angle of the arc is larger than 0 degree but up to 180 degrees, or as a minus value if the center angle is larger than 180 degrees but up to 360 degrees. The statement made above also applies to mill-line right- and mill-line left-machining units.



MAZATROL FUSION 640T



PROGRAMMING EXAMPLE No.8









MAZATROL FUSION 640T

TITLE: PROGRAMMING EXAMPLE 8



TOOLS FOR PROGRAM EXAMPLE No 8





MAZATROL FUSION 640T

UNo. MAT OD-MAX ID-MIN LENGTH RPM FIN-X FIN-Z WORK FACE
0 S45C 100. 20. 60. 3000 0.4 0.1 0.

UNo. MODE

1MTR OUT

SEQ	SHP	SPT-X	SPT-Z	FPT-X	FPT-Z	RADIUS
1	LIN	*	*	100.	40.	*
2	LIN	*	*	40.	40.	*
3	LIN	*	*	40.	60.	*

UNo. MODE # 1 # 2 # 3 # 4 # 5 # 6 # 7 # 8 # 9 #10 #11 #12
2M 8

UNo.	MODE	#	CPT-X	CPT-Z	RV	FV	R-FEED	R-DEP.	R-TOOL	F-TOOL
3	BAR OUT	0	100.	0.	375	468	0.4	5.5	1	2
SEQ	SHP	S-CNR	SPT-X	SPT-Z	FPT-X	FPT-Z	F-CNR/\$	RADIUS/Ø	ROUGH	
1	LIN	*	*	40.	30.			*	Rgh	5
2	LIN	*	*	92.	41.			*	Rgh	5

UNo.	MODE	GRV-WID	DEPTH	FIN-1	FIN-2	RV	FV	R-FR 1	R-FR 2	R-TOOL	F-TOOL
4	LFT	FCE	30.	11.	0.1	248	101	0.04	0.02	10A	10A
SEQ	SHP	FPT-R/x	FPT-An/y	FPT-Z			F-CNR	RADIUS	ROUGH		
1	STP	0.	-30.	30.				*	Rgh	5	
2	CW	-15.	-26.	*				30.	Rgh	5	
3	LIN	-37.5	-13.	*				*	Rgh	5	
4	CW	-37.5	13.	*				15.	Rgh	5	
5	LIN	-15.	26.	*				*	Rgh	5	
6	CW	15.	26.	*				30.	Rgh	5	
7	LIN	37.5	13.	*				*	Rgh	5	
8	CW	37.5	-13.	*				15.	Rgh	5	
9	LIN	15.	-26.	*				*	Rgh	5	
10	CW	0.	-30.	*				30.	Rgh	5	


UNo.	MODE	#	DIA.	DEPTH	DEP-1	DEP-2	DEP-3	V	FEED	TOOL
5	MDR	FCE	0	15.	18.	9.	3.	3.	25 0.200	11A
SEQ	SHP	SPT-R/x	SPT-An/y	SPT-Z				NUM.	ANGLE	TYPE
1	CIR	30.	0.	30.				2	180.	0

UNo. MODE COUNTER RETURN WK.No. CONT. NUM. SHIFT
6END 1 0 0 0 0.



MAZATROL FUSION 640T



PROGRAMMING EXAMPLE NO.9





MAZATROL FUSION 640T


TITLE: PROGRAMMING EXAMPLE 9



MATERIAL SIZE:
125 O/D x 60mm LONG

DRAWN BY: [] CHECKED BY:
DRAWING NUMBER:
MATERIAL: ALUMINIUM

TOOLS FOR PROGRAM EXAMPLE No 9





MAZATROL FUSION 640T

UNo.	MAT	OD-MAX	ID-MIN	LENGTH	RPM	FIN-X	FIN-Z	WORK	FACE
0	AL	125.	0.	60.	3000	0.4	0.1		0.

UNo.	MODE	# 1	# 2	# 3	# 4	# 5	# 6	# 7	# 8	# 9	#10	#11	#12
1M		8											

UNo.	MODE	GRV-WID	DEPTH	FINISH	RV	FV	R-FR 1	R-FR 2	R-TOOL	F-TOOL
2LCT	FCE	5.	5.	0.1	83	101	0.033	0.016	10B	10B
SEQ	SHP	FPT-R/x	FPT-An/y	FPT-Z			F-CNR		RADIUS	ROUGH
1	STP	47.5	3.017	0.					*	Rgh 5
2	CCW	-43.521	19.031	*					47.5	Rgh 5
3	CCW	-24.679	12.52	*					10.	Rgh 5
4	CW	-15.	0.	*					-10.	Rgh 5
5	LIN	15.	0.	*					*	Rgh 5
6	CCW	15.	-25.	*					12.5	Rgh 5
7	LIN	40.388	-25.	*					*	Rgh 5
8	CW	47.5	-176.983	*					47.5	Rgh 5

UNo.	MODE	GRV-WID	DEPTH	FINISH	RV	FV	R-FR 1	R-FR 2	R-TOOL	F-TOOL
3LCT	OUT	5.	5.	0.1	83	101	0.033	0.016	7A	7A
SEQ	SHP	FPT-R/x	FPT-An/y	FPT-Z			F-CNR		RADIUS	ROUGH
1	STP	62.5	90.	15.					*	Rgh 5
2	LIN	*	53.331	15.					*	Rgh 5
3	CCW	*	53.331	35.					10.	Rgh 5
4	LIN	*	126.669	35.					*	Rgh 5
5	CCW	*	126.669	15.					10.	Rgh 5
6	LIN	*	90.	15.					*	Rgh 5

UNo.	MODE	COUNTER	RETURN	WK.No.	CONT.	NUM.	SHIFT
4END		1	0		0	0	0.



MAZATROL FUSION 640T